Cincinnati/Northern Kentucky International Airport

Operations Memorandum

To: CVG Airport Airlines, Tenants and Concessionaires

From: Brian Cobb, Director - Customer Services

Subject: Runway 18L/36R Construction Update

Date: November 20, 2013

Construction fencing has been removed from around Runway 18L/36R. Although the runway remains closed at this time, there will be movement in and around the area until construction is complete. All security and airfield/escort requirements have been re-established and are effective immediately.

All airfield qualified personnel must follow all normal access and security procedures in the 18L/36R construction area. As a reminder, qualified airfield personnel have been issued a CVG SIDA badge with Movement Area Driving permission, as depicted in **Figure A** below.




Figure B